Form PTO 1449 (Modified)		U.S. DEPARTMENT (PATENT AND TRAD		ATTY DOCKET NO.		SERIAL NO.		
(Modified)			283276US2X PCT	10/560,353				
LICTOR	DEEE,	25N250 OLTED DV 4D0	NICANT	APPLICANT				
LISTOF	KEFEI	RENCES CITED BY APP	PLICANT	Hiroyuki OCHIAI, et al.				
				FILING DATE		GROUP		
				May 26, 2006		3742		
				U.S. PATENT DOCUMENTS				
EXAMINER INITIAL		DOCUMENT NUMBER	DATE	NAME	CLASS	SUB CLASS		
	AA							
	AB							
	AC							
	AD							
	AE							
	AF							
	AG						i i	
	AH							
	Al							
	AJ							
	AK							
	AL							
	AM					·		
	AN							
			FC	REIGN PATENT DOCUMENTS		L		
		DOCUMENT NUMBER	DATE	COUNTRY	TRANSLATION YES NO			
	AO	1272144A	11/01/2000	CHINA (copy not available, corr. to WC A1 previously filed on 03/08/2006 and of	3/08/2006 and corr. to		3	NO X
	AP			US 6,602,561 previously filed January	25, 2007)			
	AQ							
	-							
	AR							
	AS							
	AT					<u> </u>		
	AU							
	AV			<u> </u>				
OTHER REFERENCES (Including Author, Title, Date, Pertinent Pages, etc.)								
	AW	"Repair and Reinforcement of Damage of Gas Turbine Blade Caused by Water Corrosion", December 31, 1996, pages 33-35 and 39						
	AX	Huang XIAO' OU, et al., "The Electro - Spark Deposition on Damaged Bearing Section of High-Power Generator Rotator", Chinese Academy of Agricultural Machanization Sciences Material & Technology Research Institute, 2000, pages 26-29						
	AY					,		
	AZ				Additional References sheet(s) attached			
Examiner					Date Cor	e Considered		
*Examiner: In	itial if r	reference is considered.	whether or no	t citation is in conformance with MPEP 6	09; Draw li	ne through	citation	if not in
conformance and not considered. Include copy of this form with next communication to applicant.								